Documentation Errata

Document Title: Data__ADSP_2185L datasheet rev_A date_11_98

Chapter: N/A Page: 29

Revision Needed:

In the 100-Lead LQFP Package Pinout diagram (page 29) and LQFP Pin Configurations diagram (page 30), pins 37 through 40 dont show the multiplexed SPORT1 pin names. These pins should be changed to the following:

| Pin Table | |
|-----------|-----------|
| Pin# | Pin Name |
| 37 | DT1/FO |
| 38 | TFS1/IRQ1 |
| 39 | RFS1/IRQ0 |
| 40 | DR1/FI |

Prognosis: Open Reference number: 8416

Document Title: Data__ADSP_2185L datasheet rev_A date_11_98

Chapter: N/A Page: 11

Revision Needed:

In the note just before the instruction set description section, the text should change to eliminate the reference to PF3. The note should read as follows:

Note: Pins PF0, PF1, and PF2 are also used for device configuration during reset.

Prognosis: Open Reference number: 3996

Last Updated: June 19, 2003