

Product Discontinuation Notice

XCN09002 (v1.2) July 28, 2010

Product Discontinuation Notice

Overview

The purpose of this notification is to communicate that Xilinx is discontinuing all remaining members in some mature product families including: XC4000E and XC4000XLA family FPGAs; and XC1700L, XC17S00, and XC17S00XL family PROM products. Xilinx is also extending Final order and Final delivery dates for the XC1700E and XC1700EL family PROM products. This product discontinuance notice (PDN) applies to both **Commercial (C)** and **Industrial (I)** temperature grade products. This PDN does not affect the **Automotive** and **Military (defense grade)** products.

Description

As part of the Xilinx focus to continually meet customer demands, all remaining members of the XC4000E and XC4000XLA FPGA families have been scheduled for obsolescence.

The XC1700L, XC17S00, and XC17S00XL PROM families are discontinued due to the discontinuation of fabrication supply source. Note the XC17S00 and XC17S00XL PROM families are discontinued earlier than the respective Spartan® and Spartan®-XL FPGA families. Refer to the <u>Discontinuance Period Mismatch</u> <u>between Spartan/XL FPGA Families and Spartan/XL PROM Families</u> section of this notice for more information.

Xilinx is extending the Final order and Final delivery dates by about seven months for the XC1700E/EL family PROMs. These PROMs were included in the Xilinx <u>XCN09001</u> notice. This change accommodates our customers using XC4000E series FPGAs. Refer to the <u>Extension of Final Order and Final Delivery Dates for XC1700E/EL Family PROM Products</u> section of this notice for more information.

Products Affected

The products affected include all standard part numbers and specification control document (SCD) versions of the standard part numbers listed in this notice.

- <u>XC4000XLA Family FPGA Products Affected</u>
- <u>XC4000E Family FPGA Products Affected</u>
- Discontinuance Period Mismatch between Spartan/XL FPGA Families and Spartan/XL PROM Families
- Extension of Final order and Final delivery dates for XC1700E/EL series PROMs
- Fabrication Supply Source Discontinuation XC1700L and XC17S00/XL Family PROM Products Affected
- <u>Appendix A All SCD Products Affected</u>

Key Dates and Ordering Information

Final orders are accepted until November 23, 2010.

Final deliveries must occur on or before May 23, 2011.

Return Material Authorizations (RMAs) for replacement devices will be accepted until November 23, 2011.

© Copyright 2009-2010 Xilinx, Inc. XILINX, the Xilinx logo, Virtex, Spartan, ISE, and other designated brands included herein are trademarks of Xilinx in the United States and other countries. All other trademarks are the property of their respective owners.



Part Number	Replacement Part	Part Number	Replacement Part
XC4013XLA-07BG256C	No direct replacement	XC4028XLA-09BG352C	No direct replacement
XC4013XLA-07PQ208C	No direct replacement	XC4028XLA-09BG352I	No direct replacement
XC4013XLA-07PQ240C	No direct replacement	XC4028XLA-09BGG352C	No direct replacement
XC4013XLA-08BG256C	No direct replacement	XC4036XLA-07BG352C	No direct replacement
XC4013XLA-08BG256I	No direct replacement	XC4036XLA-07BG432C	No direct replacement
XC4013XLA-08PQ208C	No direct replacement	XC4036XLA-08BG352C	No direct replacement
XC4013XLA-08PQ208I	No direct replacement	XC4036XLA-08BG352I	No direct replacement
XC4013XLA-08PQ240C	No direct replacement	XC4036XLA-08BG432C	No direct replacement
XC4013XLA-08PQ240I	No direct replacement	XC4036XLA-08BG432I	No direct replacement
XC4013XLA-09BG256C	No direct replacement	XC4036XLA-09BG352C	No direct replacement
XC4013XLA-09BG256I	No direct replacement	XC4036XLA-09BG352I	No direct replacement
XC4013XLA-09PQ208C	No direct replacement	XC4036XLA-09BG432C	No direct replacement
XC4013XLA-09PQ208I	No direct replacement	XC4036XLA-09BG432I	No direct replacement
XC4013XLA-09PQ240C	No direct replacement	XC4052XLA-07BG352C	No direct replacement
XC4013XLA-09PQ240I	No direct replacement	XC4052XLA-07BG432C	No direct replacement
XC4020XLA-07BG256C	No direct replacement	XC4052XLA-08BG352C	No direct replacement
XC4020XLA-07PQ208C	No direct replacement	XC4052XLA-08BG352I	No direct replacement
XC4020XLA-07PQ240C	No direct replacement	XC4052XLA-08BG432C	No direct replacement
XC4020XLA-08BG256C	No direct replacement	XC4052XLA-08BG432I	No direct replacement
XC4020XLA-08BG256I	No direct replacement	XC4052XLA-09BG352C	No direct replacement
XC4020XLA-08PQ208C	No direct replacement	XC4052XLA-09BG352I	No direct replacement
XC4020XLA-08PQ208I	No direct replacement	XC4052XLA-09BG432C	No direct replacement
XC4020XLA-08PQ240C	No direct replacement	XC4052XLA-09BG432I	No direct replacement
XC4020XLA-08PQ240I	No direct replacement	XC4085XLA-07BG352C	No direct replacement
XC4020XLA-09BG256C	No direct replacement	XC4085XLA-07BG432C	No direct replacement
XC4020XLA-09BG256I	No direct replacement	XC4085XLA-07BG560C	No direct replacement
XC4020XLA-09PQ208C	No direct replacement	XC4085XLA-08BG352C	No direct replacement
XC4020XLA-09PQ208I	No direct replacement	XC4085XLA-08BG352I	No direct replacement
XC4020XLA-09PQ240C	No direct replacement	XC4085XLA-08BG432C	No direct replacement
XC4020XLA-09PQ240I	No direct replacement	XC4085XLA-08BG432I	No direct replacement
XC4020XLA-09PQG240C	No direct replacement	XC4085XLA-08BG560C	No direct replacement
XC4028XLA-07BG256C	No direct replacement	XC4085XLA-08BG560I	No direct replacement
XC4028XLA-07BG352C	No direct replacement	XC4085XLA-09BG352C	No direct replacement
XC4028XLA-08BG256C	No direct replacement	XC4085XLA-09BG352I	No direct replacement
XC4028XLA-08BG256I	No direct replacement	XC4085XLA-09BG432C	No direct replacement
XC4028XLA-08BG352C	No direct replacement	XC4085XLA-09BG432I	No direct replacement
XC4028XLA-08BG352I	No direct replacement	XC4085XLA-09BG560C	No direct replacement
XC4028XLA-09BG256C	No direct replacement	XC4085XLA-09BG560I	No direct replacement
XC4028XLA-09BG256I	No direct replacement	XC4085XLA-09BGG352C	No direct replacement

Table 2: XC4000E Family FPGA Products Affected

Part Number	Replacement Part	Part Number
XC4005E-1PC84C	No direct replacement	XC4010E-3PC84
XC4005E-1PQ100C	No direct replacement	XC4010E-3PC84
XC4005E-1PQ160C	No direct replacement	XC4010E-3PQ16
XC4005E-1TQ144C	No direct replacement	XC4010E-3PQ16
XC4005E-2PC84C	No direct replacement	XC4010E-3PQ20
XC4005E-2PC84I	No direct replacement	XC4010E-3PQ20
XC4005E-2PQ100C	No direct replacement	XC4010E-4BG22
XC4005E-2PQ100I	No direct replacement	XC4010E-4BG22
XC4005E-2PQ160C	No direct replacement	XC4010E-4PC84
XC4005E-2PQ160I	No direct replacement	XC4010E-4PC84
XC4005E-2TQ144C	No direct replacement	XC4010E-4PQ16
XC4005E-2TQ144I	No direct replacement	XC4010E-4PQ16
XC4005E-3PC84C	No direct replacement	XC4010E-4PQ20
XC4005E-3PC84I	No direct replacement	XC4010E-4PQ20
XC4005E-3PQ100C	No direct replacement	XC4013E-1BG22
XC4005E-3PQ100I	No direct replacement	XC4013E-1PQ16
XC4005E-3PQ160C	No direct replacement	XC4013E-1PQ20
XC4005E-3PQ160I	No direct replacement	XC4013E-1PQ24
XC4005E-3TQ144C	No direct replacement	XC4013E-2BG22
XC4005E-3TQ144I	No direct replacement	XC4013E-2BG22
XC4005E-4PC84C	No direct replacement	XC4013E-2PQ16
XC4005E-4PC84I	No direct replacement	XC4013E-2PQ16
XC4005E-4PQ100C	No direct replacement	XC4013E-2PQ20
XC4005E-4PQ100I	No direct replacement	XC4013E-2PQ20
XC4005E-4PQ160C	No direct replacement	XC4013E-2PQ24
XC4005E-4PQ160I	No direct replacement	XC4013E-2PQ24
XC4005E-4TQ144C	No direct replacement	XC4013E-3BG22
XC4005E-4TQ144I	No direct replacement	XC4013E-3BG22
XC4010E-1BG225C	No direct replacement	XC4013E-3PQ16
XC4010E-1PC84C	No direct replacement	XC4013E-3PQ16
XC4010E-1PQ160C	No direct replacement	XC4013E-3PQ20
XC4010E-1PQ208C	No direct replacement	XC4013E-3PQ20
XC4010E-2BG225C	No direct replacement	XC4013E-3PQ24
XC4010E-2BG225I	No direct replacement	XC4013E-3PQ24
XC4010E-2PC84C	No direct replacement	XC4013E-4BG22
XC4010E-2PC84I	No direct replacement	XC4013E-4BG22
XC4010E-2PQ160C	No direct replacement	XC4013E-4PQ16
XC4010E-2PQ160I	No direct replacement	XC4013E-4PQ16
XC4010E-2PQ208C	No direct replacement	XC4013E-4PQ20
XC4010E-2PQ208I	No direct replacement	XC4013E-4PQ20
XC4010E-3BG225C	No direct replacement	XC4013E-4PQ24
XC4010E-3BG225I	No direct replacement	XC4013E-4PQ24

Part Number	Replacement Part		
XC4010E-3PC84C	No direct replacement		
XC4010E-3PC84I	No direct replacement		
XC4010E-3PQ160C	No direct replacement		
XC4010E-3PQ160I	No direct replacement		
XC4010E-3PQ208C	No direct replacement		
XC4010E-3PQ208I	No direct replacement		
XC4010E-4BG225C	No direct replacement		
XC4010E-4BG225I	No direct replacement		
XC4010E-4PC84C	No direct replacement		
XC4010E-4PC84I	No direct replacement		
XC4010E-4PQ160C	No direct replacement		
XC4010E-4PQ160I	No direct replacement		
XC4010E-4PQ208C	No direct replacement		
XC4010E-4PQ208I	No direct replacement		
XC4013E-1BG225C	No direct replacement		
XC4013E-1PQ160C	No direct replacement		
XC4013E-1PQ208C	No direct replacement		
XC4013E-1PQ240C	No direct replacement		
XC4013E-2BG225C	No direct replacement		
XC4013E-2BG225I	No direct replacement		
XC4013E-2PQ160C	No direct replacement		
XC4013E-2PQ160I	No direct replacement		
XC4013E-2PQ208C	No direct replacement		
XC4013E-2PQ208I	No direct replacement		
XC4013E-2PQ240C	No direct replacement		
XC4013E-2PQ240I	No direct replacement		
XC4013E-3BG225C	No direct replacement		
XC4013E-3BG225I	No direct replacement		
XC4013E-3PQ160C	No direct replacement		
XC4013E-3PQ160I	No direct replacement		
XC4013E-3PQ208C	No direct replacement		
XC4013E-3PQ208I	No direct replacement		
XC4013E-3PQ240C	No direct replacement		
XC4013E-3PQ240I	No direct replacement		
XC4013E-4BG225C	No direct replacement		
XC4013E-4BG225I	No direct replacement		
XC4013E-4PQ160C	No direct replacement		
XC4013E-4PQ160I	No direct replacement		
XC4013E-4PQ208C	No direct replacement		
XC4013E-4PQ208I	No direct replacement		
XC4013E-4PQ240C	No direct replacement		
XC4013E-4PQ240I	No direct replacement		

Extension of Final Order and Final Delivery Dates for XC1700E/EL Family PROM Products

Xilinx is extending the Final order and Final delivery dates by about seven months for the XC1700E/EL family PROMs. These PROMs were included in the Xilinx <u>XCN09001</u> notice. This change accommodates our customers using XC4000E series FPGAs. The revised date is summarized in Table 3 and the affected parts are shown in Table 4.

	Old Date (as per <u>XCN09001</u>)	New Date (as per XCN09002)
Final orders	April 27, 2010	November 23, 2010
Final deliveries	October 27, 2010	May 23, 2011

Table 3: XC1700E/EL Family PROMs Date Extension

Table 4: XC1700E/EL Family PROM Products Affected

Part Number	Replacement Part	Part Number	Replacement Part
XC17128ELPC20C	No direct replacement	XC1736EPC20I	No direct replacement
XC17128ELPC20I	No direct replacement	XC1736EPD8C	No direct replacement
XC17128ELPD8C	No direct replacement	XC1736EPD8I	No direct replacement
XC17128ELPD8I	No direct replacement	XC1736EPDG8C	No direct replacement
XC17128ELVO8C	No direct replacement	XC1736ESO8C	No direct replacement
XC17128ELVO8I	No direct replacement	XC1736ESO8I	No direct replacement
XC17128EPC20C	No direct replacement	XC1736ESOG8C	No direct replacement
XC17128EPC20I	No direct replacement	XC1736EVO8C	No direct replacement
XC17128EPCG20C	No direct replacement	XC1736EVO8I	No direct replacement
XC17128EPD8C	No direct replacement	XC1736EVOG8C	No direct replacement
XC17128EPD8I	No direct replacement	XC1765ELPC20C	No direct replacement
XC17128EPDG8C	No direct replacement	XC1765ELPC20I	No direct replacement
XC17128EVO8C	No direct replacement	XC1765ELPD8C	No direct replacement
XC17128EVO8I	No direct replacement	XC1765ELPD8I	No direct replacement
XC17128EVOG8C	No direct replacement	XC1765ELSO8C	No direct replacement
XC17256ELPC20C	No direct replacement	XC1765ELSO8I	No direct replacement
XC17256ELPC20I	No direct replacement	XC1765ELSOG8C	No direct replacement
XC17256ELPD8C	No direct replacement	XC1765ELVO8C	No direct replacement
XC17256ELPD8I	No direct replacement	XC1765ELVO8I	No direct replacement
XC17256ELVO8C	No direct replacement	XC1765ELVOG8C	No direct replacement
XC17256ELVO8I	No direct replacement	XC1765EPC20C	No direct replacement
XC17256EPC20C	No direct replacement	XC1765EPC20I	No direct replacement
XC17256EPC20I	No direct replacement	XC1765EPD8C	No direct replacement
XC17256EPCG20C	No direct replacement	XC1765EPD8I	No direct replacement
XC17256EPD8C	No direct replacement	XC1765EPDG8C	No direct replacement
XC17256EPD8I	No direct replacement	XC1765ESO8C	No direct replacement
XC17256EPDG8C	No direct replacement	XC1765ESO8I	No direct replacement
XC17256EVO8C	No direct replacement	XC1765ESOG8C	No direct replacement
XC17256EVO8I	No direct replacement	XC1765EVO8C	No direct replacement
XC1736EPC20C	No direct replacement	XC1765EVO8I	No direct replacement

Discontinuance Period Mismatch between Spartan/XL FPGA Families and Spartan/XL **PROM Families**

Some customers use XC17S00 and XC17S00XL PROM families to configure the Spartan and Spartan-XL FPGA families respectively. Both of these PROM families are being discontinued before the corresponding FPGA families. The planned PDN release date is Q4 of 2010 for the Spartan FPGA family and Q2 of 2011 for the Spartan-XL FPGA family. Customers using these PROM families for Spartan and Spartan-XL FPGAs must pre-order the PROM parts by the Final order date mentioned in the Key Dates and Ordering Information section of this notice. The mismatch in discontinuance between PROMs and FPGAs is summarized in Table 5 and the list of all affected parts is shown in Table 6.

PROM Family (PDN Date)	Corresponding FPGA Family (PDN Date)	
XC17S00 (November 23, 2009)	Spartan (Planned for Q4 2010)	
XC17S00XL (November 23, 2009)	Spartan-XL (Planned for Q2 2011)	

Fabrication Supply Source Discontinuance Parts Affected

	OL Family	Ī		S00 Family
Part Number	Replacement Part		Part Number	Replacement Part
XC1701LPC20C	No direct replacement		XC17S05PD8C	No direct replacement
XC1701LPC20I	No direct replacement		XC17S05PD8I	No direct replacement
XC1701LPCG20C	No direct replacement		XC17S05VO8C	No direct replacement
XC1701LPCG20I	No direct replacement		XC17S05VO8I	No direct replacement
XC1701LPD8C	No direct replacement		XC17S10PD8C	No direct replacement
XC1701LPD8I	No direct replacement		XC17S10PD8I	No direct replacement
XC1701LPDG8C	No direct replacement		XC17S10VO8C	No direct replacement
XC1701LPDG8I	No direct replacement		XC17S10VO8I	No direct replacement
XC1701LSO20C	No direct replacement		XC17S10VOG8C	No direct replacement
XC1701LSO20I	No direct replacement		XC17S20PD8C	No direct replacement
XC1702LPC44C	No direct replacement		XC17S20PD8I	No direct replacement
XC1702LPC44I	No direct replacement		XC17S20VO8C	No direct replacement
XC1702LVQ44C	No direct replacement		XC17S20VO8I	No direct replacement
XC1702LVQ44I	No direct replacement		XC17S30PD8C	No direct replacement
XC1704LPC44C	No direct replacement		XC17S30PD8I	No direct replacement
XC1704LPC44I	No direct replacement		XC17S30SOG8I	No direct replacement
XC1704LVQ44C	No direct replacement		XC17S30VO8C	No direct replacement
XC1704LVQ44I	No direct replacement		XC17S30VO8I	No direct replacement
XC17512LPC20C	No direct replacement		XC17S40PD8C	No direct replacement
XC17512LPC20I	No direct replacement		XC17S40PD8I	No direct replacement
XC17512LPD8C	No direct replacement		XC17S40SO20C	No direct replacement
XC17512LPD8I	No direct replacement		XC17S40SO20I	No direct replacement
XC17512LSO20C	No direct replacement			
XC17512LSO20I	No direct replacement			

Table 6: XC1700L & XC17S00/XL Family PROM Products Affected

XC17S30XLVO8I

XC17S30XLVOG8C

XC17S30XLVOG8I

Table 6 (Continued): XC1700L & XC17S00/XL Family PROM Products Affected

No direct replacement

No direct replacement

No direct replacement

XC17S00XL Family				
Part Number	Replacement Part		Part Number	Replacement Part
XC17S05XLPD8C	No direct replacement] [XC17S40XLPD8C	No direct replacement
XC17S05XLPD8I	No direct replacement		XC17S40XLPD8I	No direct replacement
XC17S05XLVO8C	No direct replacement		XC17S40XLPDG8C	No direct replacement
XC17S05XLVO8I	No direct replacement		XC17S40XLSO20C	No direct replacement
XC17S10XLPD8C	No direct replacement] [XC17S40XLSO20I	No direct replacement
XC17S10XLPD8I	No direct replacement] [XC17S50XLPD8C	No direct replacement
XC17S10XLPDG8C	No direct replacement] [XC17S50XLPD8I	No direct replacement
XC17S10XLVO8C	No direct replacement] [XC17S50XLSO20C	No direct replacement
XC17S10XLVO8I	No direct replacement] [XC17S50XLSO20I	No direct replacement
XC17S10XLVOG8C	No direct replacement		XC17S100XLPD8C	No direct replacement
XC17S10XLVOG8I	No direct replacement] [XC17S100XLPD8I	No direct replacement
XC17S20XLPD8C	No direct replacement] [XC17S100XLSO20C	No direct replacement
XC17S20XLPD8I	No direct replacement		XC17S100XLSO20I	No direct replacement
XC17S20XLVO8C	No direct replacement] [XC17S150XLPD8C	No direct replacement
XC17S20XLVO8I	No direct replacement	JC	XC17S150XLPD8I	No direct replacement
XC17S20XLVOG8C	No direct replacement		XC17S150XLSO20C	No direct replacement
XC17S30XLPD8C	No direct replacement	JC	XC17S150XLSO20I	No direct replacement
XC17S30XLPD8I	No direct replacement]		
XC17S30XLPDG8C	No direct replacement]		
XC17S30XLVO8C	No direct replacement			
		1		

www.xilinx.com

Appendix A – All SCD Products Affected

Table 7: XC4000E Family FPGA Products Affected

Part Number	Replacement Part
XC4005E-3TQ144C0629	No direct replacement
XC4005E-4PQ100C0280	No direct replacement
XC4005E-4PQ160C0710	No direct replacement
XC4010E-3PC84I0377	No direct replacement
XC4010E-3PQ208C0280	No direct replacement
XC4010E-3PQ208C0314	No direct replacement
XC4010E-4PQ160I0377	No direct replacement
XC4013E-1PQ208C0436	No direct replacement

Part Number	Replacement Part
XC4013E-2BG225I0262	No direct replacement
XC4013E-2PQ208C0680	No direct replacement
XC4013E-2PQ240I0262	No direct replacement
XC4013E-3PQ208C0280	No direct replacement
XC4013E-3PQ240C0377	No direct replacement
XC4013E-4PQ160C0280	No direct replacement
XC4013E-4PQ208I0377	No direct replacement

Table 8: XC4000XLA Family FPGA Products Affected

Part Number	Replacement Part	Part Number	Replacement Part
XC4020XLA-09BG256I0262	No direct replacement	XC4085XLA-09BG352I0262	No direct replacement
XC4028XLA-09BG256C0716	No direct replacement	XC4085XLA-09BG432C0280	No direct replacement

Table 9: XC1700L & XC17S00/XL Family PROM Products Affected

XC1700L Family		
Part Number	Replacement Part	
XC1701LPC20C0100	No direct replacement	
XC1701LPC20C0641	No direct replacement	
XC1701LPC20I0100	No direct replacement	
XC1701LPC20I0280	No direct replacement	
XC1701LPD8C0280	No direct replacement	
XC1701LPD8C0611	No direct replacement	
XC1701LSO20C0100	No direct replacement	
XC1701LSO20C0280	No direct replacement	
XC1701LSO20C0530	No direct replacement	
XC1701LSO20C0736	No direct replacement	
XC1702LPC44C0100	No direct replacement	
XC1704LPC44C0100	No direct replacement	
XC1704LVQ44C0100	No direct replacement	
XC17512LPC20C0280	No direct replacement	
XC17512LPD8C0609	No direct replacement	
XC17512LPD8I0280	No direct replacement	
XC17512LSO20C0736	No direct replacement	

XC17S00/XL Family		
Part Number	Replacement Part	
XC17S10PD8C0280	No direct replacement	
XC17S10PD8C0520	No direct replacement	
XC17S10VO8C0530	No direct replacement	
XC17S20PD8C0280	No direct replacement	
XC17S20VO8C0100	No direct replacement	
XC17S20VO8C0280	No direct replacement	
XC17S20VO8I0100	No direct replacement	
XC17S30PD8C0280	No direct replacement	
XC17S30VO8C0100	No direct replacement	
XC17S40PD8C0280	No direct replacement	
XC17S40PD8C0520	No direct replacement	
XC17S05XLVO8I0100	No direct replacement	
XC17S10XLPD8C0280	No direct replacement	
XC17S10XLVO8C0100	No direct replacement	
XC17S10XLVO8C0280	No direct replacement	
XC17S20XLPD8C0280	No direct replacement	
XC17S20XLVO8C0100	No direct replacement	
XC17S20XLVO8I0100	No direct replacement	
XC17S20XLVOG8C0100	No direct replacement	
XC17S30XLPD8C0280	No direct replacement	
XC17S30XLVO8C0100	No direct replacement	
XC17S40XLPD8C0280	No direct replacement	
XC17S40XLSO20C0280	No direct replacement	
XC17S40XLSO20I0100	No direct replacement	
XC17S100XLSO20C0100	No direct replacement	
XC17S150XLSO20C0100	No direct replacement	

Part Number	Replacement Part		Part Number	Replacement Part
XC17128EPC20C0100	No direct replacement		XC1736EPC20C0100	No direct replacement
XC17128EPC20C0280	No direct replacement		XC1736EPC20C0280	No direct replacement
XC17128EPC20I0100	No direct replacement		XC1736EPC20C0520	No direct replacement
XC17128EPD8C0280	No direct replacement		XC1736EPC20I0100	No direct replacement
XC17256ELPC20I0100	No direct replacement		XC1736EPD8C0280	No direct replacement
XC17256ELVO8C0100	No direct replacement	-	XC1736EPD8C0520	No direct replacement
XC17256ELVO8C0280	No direct replacement		XC1736ESO8C0100	No direct replacement
XC17256ELVO8C0530	No direct replacement		XC1736ESO8I0100	No direct replacement
XC17256EPC20C0520	No direct replacement		XC1765EPC20C0100	No direct replacement
XC17256EPC20I0100	No direct replacement		XC1765EPC20I0100	No direct replacement
XC17256EPD8C0280	No direct replacement		XC1765EPD8C0280	No direct replacement
XC17256EPD8C0520	No direct replacement		XC1765EPD8C0520	No direct replacement
XC17256EVO8I0100	No direct replacement		XC1765EVO8I0100	No direct replacement

Table 10: XC1700E/EL Family PROM Products Affected

Response

Customers are requested to place last-time-buy orders in a timely manner prior to the key dates listed above to avoid product availability issues. If you anticipate that your last time buy requirements will exceed the current rate, please provide your Xilinx Sales Representative with a forecast of the requirements. All orders will be supported on a first-come, first-served basis with the non-cancellable and non-returnable (NCNR) condition. For additional information or questions, contact your local Xilinx Sales representative.

Important Notice: Xilinx Customer Notifications (XCNs, XDNs, and Quality Alerts) can be delivered via e-mail alerts sent by the Support website (<u>http://www.xilinx.com/support</u>). Register today and personalize your "Documentation and Design Advisory Alerts" area to include Customer Notifications. Xilinx Support provides many benefits, including the ability to receive alerts for new and updated information about specific products, as well as alerts for other publications such as data sheets, errata, application notes, etc. For information on how to sign up, refer to Xilinx Answer Record 18683.

Revision History

Date	Version	Revision
11/23/2009	1.0	Initial release.
12/21/2009	1.1	Added <u>Table 10</u> ; updated <u>Table 1</u> and <u>Table 4</u> to add missing parts.
07/19/2010	1.1.1	Corrected typo on Table 10 from XC1754EVO8I0100 to XC1765EVO8I0100.
07/28/2010	1.2	Added missing part 'XC4085XLA-09BGG352C' back to Table 1.

The following table shows the revision history for this document.



Notice of Disclaimer

THE XILINX HARDWARE FPGA AND CPLD DEVICES REFERRED TO HEREIN ("PRODUCTS") ARE SUBJECT TO THE TERMS AND CONDITIONS OF THE XILINX LIMITED WARRANTY WHICH CAN BE VIEWED AT http://www.xilinx.com/warranty.htm. THIS LIMITED WARRANTY DOES NOT EXTEND TO ANY USE OF PRODUCTS IN AN APPLICATION OR ENVIRONMENT THAT IS NOT WITHIN THE SPECIFICATIONS STATED ON THE XILINX DATA SHEET. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE. PRODUCTS ARE NOT DESIGNED OR INTENDED TO BE FAIL-SAFE, OR FOR USE IN ANY APPLICATION REQUIRING FAIL-SAFE PERFORMANCE, SUCH AS LIFESUPPORT OR SAFETY DEVICES OR SYSTEMS, OR ANY OTHER APPLICATION THAT INVOKES THE POTENTIAL RISKS OF DEATH, PERSONAL INJURY OR PROPERTY OR ENVIRONMENTAL DAMAGE ("CRITICAL APPLICATIONS"). USE OF PRODUCTS IN CRITICAL APPLICATIONS IS AT THE SOLE RISK OF CUSTOMER, SUBJECT TO CHANGE WITHOUT NOTICE.