

# Product/Process Change Notice - PCN 15\_0205 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

**PCN Title:** ADG5412F/ADG5413F, ADG5412BF/ADG5413BF, ADG5404F, ADG5436F and

ADG5462F Datasheet Specification Change

Publication Date: 14-Oct-2015

Effectivity Date: 12-Jan-2016 (the earliest date that a customer could expect to receive changed material)

Description:

Initial Release

## **Description Of Change**

Changes to the datasheet specification regarding OFF and ON Leakage and in some cases Leakage current with over-voltage. The following product datasheets are affected: ADG5412F/ADG5413F, ADG5412BF/ADG5413BF, ADG5404F, ADG5436F and the ADG5462F. Please see attachment for full change details.

### Reason For Change

To accurately reflect the capability of the devices.

# Impact of the change (positive or negative) on fit, form, function & reliability

There will be no impact on form, fit, function, quality or reliability of any of the products.

Product Identification (this section will describe how to identify the changed material)

The change over date code will be advised on a future revision of this PCN.

## **Summary of Supporting Information**

These specification changes will be outlined in Rev B of the affected devices' data sheets.

### Supporting Documents

Attachment 1: Type: Datasheet Specification Comparison

ADI\_PCN\_15\_0205\_Rev\_-\_ADG5412F Family PCN Specification Change Document.pdf

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN Americas@analoq.com Europe: PCN Europe@analoq.com Japan: PCN Japan@analoq.com

Rest of Asia: PCN\_ROA@analog.com

Appendix A - Affected ADI Models						
Added Parts On This Revision - Product Family / Model Number (21)						
ADG5404F / ADG5404FBCPZ-RL7	ADG5404F / ADG5404FBRUZ	ADG5404F / ADG5404FBRUZ-RL7	ADG5412BF / ADG5412BFBCPZ-RL7	ADG5412BF / ADG5412BFBRUZ		
ADG5412BF / ADG5412BFBRUZ-RL7	ADG5412F / ADG5412FBCPZ-RL7	ADG5412F / ADG5412FBRUZ	ADG5412F / ADG5412FBRUZ-RL7	ADG5413BF / ADG5413BFBCPZ-RL7		
ADG5413BF / ADG5413BFBRUZ	ADG5413BF / ADG5413BFBRUZ-RL7	ADG5413F / ADG5413FBCPZ-RL7	ADG5413F / ADG5413FBRUZ	ADG5413F / ADG5413FBRUZ-RL7		
ADG5436F / ADG5436FBCPZ-RL7	ADG5436F / ADG5436FBCPZ-RL7 ADG5436F / ADG5436FBRUZ		ADG5462F / ADG5462FBCPZ-RL7	ADG5462F / ADG5462FBRUZ		
ADG5462F / ADG5462FBRUZ-RL7						

Appendix B - Revision History				
Rev	Publish Date	Effectivity Date	Rev Description	
Rev	14-Oct-2015	12-Jan-2016	Initial Release	

Analog Devices, Inc.

DocId:3435 Parent DocId:None Layout Rev:7