onsemi

Product Bulletin Document #: PB24207X2

Issue Date: 07 Oct 2022

Title of Changes	Lindete for DD24207V. To identify encoding sites offected with the change including the transition period		
Title of Change:	Update for PB24207X - To identify specific sites affected with the change including the transition period.		
Effective date:	07 Oct 2022		
Contact information:	Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com		
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.		
Change Category:	Test Change		
Change Sub-Category(s):	Shipping/Packaging/Marking		
Sites Affected:			
onsemi Sites		External Foundry/Subcon Sites	
onsemi Cebu, Philippines		Greatek Electronics Inc., Taiwan	
onsemi Leshan, China		HANA Microelectronics, China	
onsemi Seremban, Malaysia		JCET, China	
Description and Purpose:			

This update to PB24207X is to list all of the affected sites and clarify that the transition period will be until Dec 31,2022.


SOSM and SOT223 package assembled in various listed sites will start to use onsemi Marking Layout Configuration

This is part of the alignment and marking standardization.

For a specific OPN that is build in different sites will now have the same lay out scheme and will just differ on the plant code.

Sample marking change below.

Fairchild Marking





ON Semi Marking



AYW XXXXX

Legend: X = Device Mark M = Month Code A = Plant Code Y = Year Code W = Week Code

Note: This information is generic. Please refer to device data sheet for actual part marking. Pin1 indicator, Pb–Free indicator, microdot, may or may not be present. Some products may not follow the Generic Marking.

onsemi

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

FDC6303N	FDC6305N
FDC6310P	FDC6312P
FDC6321C	FDC6323L
FDC6325L	FDC6326L
FDC6329L	FDC658AP
FDC655BN-G	FDC654P
FDC645N	FDC6420C
FDC6401N	FDC638P-P
FDC638APZ-SBMS001	FDC638APZ-PSBMS001
FDC634P	FDC6333C-G
FDC6331L	FDC6330L
FDC606P	FDC604P
FDC5661N-F085	FDC5614P
FDC3612	FDC3601N
FDC30N20DZ	FDC2612
FDC2512	FDC013P20L
	FDC6310P FDC6321C FDC6325L FDC6329L FDC655BN-G FDC645N FDC6401N FDC638APZ-SBMS001 FDC6331L FDC6331L FDC666P FDC5661N-F085 FDC3612 FDC30N20DZ